**StarTech.com**
Hard-to-find **made easy**®

## USB-C Multiport Adapter - Dual HDMI 4K 60Hz - USB-C and USB-A, GbE, SD 4.0 (UHS-II) - 100W PD

Product ID
102B-USBC-MULTIPORT

Product Diagram (Side A)

(Side B)

(Side C)

	Component	Function
1	Built-in USB-C Host Cable	• Connect to a USB-C Port on a Host Laptop • USB 3.2 Gen 2 (10Gbps) • Power Delivery 3.0 Specification
2	USB-C Data Port	• Connect a USB-C peripheral • USB 3.2 Gen 2 (10Gbps)

3	USB-A Data/Charge Port	• Connect and/or charge a USB-A peripheral • USB 3.2 Gen 2 (10Gbps) • Supports BC1.2 5V/1.5A (7.5W) • USB-C Power Adapter required for charging
4	SD Card Reader	• Secure Digital (SD) 4.0 UHS-II, SD 3.0, 2.0, 1.1, and 1.0 compatibility • Push an SD Card, label side up, into the SD • Card Slot • Note: The Host Computer's Operating System (OS) will automatically detect the SD Card and install the required driver software • Pull the SD Card to remove
5	2 x HDMI Output Ports	• Connect to HDMI Display Devices • HDMI 2.0 • Up to 4K (4096x2160) 60Hz
6	Gb Ethernet Port	• Connect a CAT 5e/CAT 6 cable to establish a network connection • 10/100/1000Mbps
7	USB-C 100W Power Delivery Port	• Connect a USB-C power adapter • USB Power Delivery 3.0

Requirements

For the latest requirements, please visit www.StarTech.com/102B-USBC-MULTIPORT

Installation

Side A Ports

1. If you have a Windows computer with Internet access, connect the Built-in USB-C Host Cable on the Multiport Adapter to a USB-C port on your host laptop. Your computer will automatically detect the device and install all the required drivers.

    If you're running a non-Windows operating system or the drivers do not automatically install, disconnect the device from your computer, then:

    a. Navigate to www.StarTech.com/102B-USBC-MULTIPORT and click the **Drivers/Downloads** tab.

    b. Under **Driver(s)**, download the Driver Package for your operating system, and follow the steps outlined in the Installation guide, that's included in the Driver Package.

2. When connecting USB peripheral devices, connect a USB-C cable from your USB peripheral device to the **USB-C Data Port** on the Multiport Adapter.

    Note: The USB port will output whatever bus power is available, up to 4.5W.

3. Connect a USB-A cable from your USB peripheral device to the **USB-A Data/Charge Port** on the Multiport Adapter, to connect the device to your computer, and/or charge your device with up to 5V/1.5A (7.5W).

    Notes:

    - A USB-C power adapter must be connected to the 100W Power Delivery Port on the Multiport adapter, in order to charge connected peripheral devices.

    - Without a power adapter connected, the USB port will output whatever bus power is available, up to 4.5W.

4. Insert your memory card into the SD Card Reader, and press the card to lock it into place. Your computer will recognize the card and mount it as a drive on your connected host computer. To remove the memory card, push the card in and then pull the memory card out.

    Note: To protect your memory card and the data stored on it, it's important to safely unmount (eject) the card within your computer's operating system, before physically removing the card from the Multiport Adapter.

Side B Ports

StarTech.com Ltd.	StarTech.com LLP	StarTech.com Ltd.	StarTech.com Ltd.	FR: startech.com/fr
45 Artisans Cres	4490 South Hamilton Road	Unit B, Pinnacle 15 Gowerton Rd, Brackmills	Siriusdreef 17-27 2132 WT Hoofddorp The Netherlands	DE: startech.com/de
London, Ontario	Groveport, Ohio	Northampton		ES: startech.com/es
N5V 5E9	43125	NN4 7BW		NL: startech.com/nl
Canada	U.S.A.	United Kingdom		IT: startech.com/it
				JP: startech.com/jp

Installation Cont'd

5. Connect an HDMI cable from up to two HDMI enabled display devices, to the **HDMI Output Ports** on the Multiport Adapter, to add additional HDMI displays to your workstation.

6. Connect a CAT 5e/CAT 6 cable from your local area network (e.g. Router, Switch, Modem, etc.) to the **Gb Ethernet Port** on the Multiport Adapter, to access your network via a wired LAN connection.

Side C Ports

7. Connect a USB-C power adapter (up to 100W) from an AC outlet to the **USB-C 100W Power Delivery Port** on the Multiport Adapter, to charge the laptop that's connected to **Built-in USB-C Host Cable**.