## **Material Safety Data Sheet**

No. 3G169

IDENTITY (As Used or Label a	Note:	e: Blank spaces are not permitted. If any item is not applicable.Or no information is available,the space must be marked to indicate that.			
Section 1					
Quantum International					
932685 5 Star Correction	n Roller				
934203 5 Star Mini Corr	ection Roller				
934207 5 Star Side Corre	ection Roller				
Section 2 Hazardous Ingr	edients/Ide	entity Info	ormation		
Hazardous Components (Specific Chemical I	dentity: Common N	Names(S) OS	HA PEL ACGIH TL	Other Limite Recommended	%(optional)
Identity Inforation	wt%				
Pigment	70				
Resin	20				
Surfactant	10				
Hazardous Ingredients					
Section 3- Physical/Chemical	 Characteristi	ics			
Bailing Point		1	Gravity(H <sub>2</sub> O=	1)	1.5
Vapor Pressure(Pa)		Malting I	Point		
Vapor density (AIR=1)			tion Rate(Buty	Acstate=1)	
Solubility in Water	Insoluble				
Appearance and Odor	White, A bi	t of Scent	ed		
Section 4- Fire and Explo-	stion Haza	rd Data			
Flash Point (Method Used)		Flamma	ole Limits	LEL 	UEL
Extinguishing Media	Water / Wat	er spray,	Foam , Dry ch	emical	
Special Fire Fighting Precedur		None	·		
Unusual Fire and Explosion H	axard	None			
"" No Data		. 10.10			

Section 5 -	Reactivity D	Data		
Stability	Unstable		Conditions to Avoid	
	Stable	0		
Incompatibili	ty(Materials to	Avoid)		
			None	
Hazardous	May Occur			
Polymerization	Will not Occı	0	None	
Section 6 -	Health Haz	zard Data	1	
Route of Entry		Inhalation	Skin? In	gestion?
			0	0
Health Haza	rds(Acute and	l Chrovnic		
			None	
			None	
Carcinoganio	city	NTP	LARC Monographs?	OSHA Regulated
		None	None	None
Sign and Syr	mptome of Ex	posure		
			None	
Medical Con	dition Genera	Ilv Aggrav	ated by Exposure	
		, 00	None	
F	and First Aid D			
Emergency a	and Fist Aid P	rocedures		
""No Data				

Section 7	7 - Precaution for Safe Han	dling and Use			
Step to B	e Taken in Case Material i	s Released or Spilled			
	Wash with water				
Waste Di	sposal Method				
	When Small waste is burn	nt; contain waste with sawdust or wastes and			
	burn in a open-type incinerator.				
	Follow all relevant regulat	tion for disposal			
Danasatia	on to De Talon in Hamilian	and Otarian			
Precautio	on to Be Taken in Handling	and Storing			
-	Store warehouse at norm	al temperature, Avoid excessive moisture.			
	Store warehouse at norm	ai temperature, Avoid excessive moisture.			
Other Pre	ecaustions				
		None			
Section 8	3 - Control Measures				
Respirato	ory protestion(Specify Type				
·		,			
		Not required			
		·			
	Local Exhaust	Not required			
Ventiletion	Mechanical(General)	Not required			
Veritiletioi	Special	Not required			
	Other	Not required			
Protective	e Gloves				
		Not required			
Eye Proe	ection				
		Not required			
Other Pro	otective Clothing or Equipm				
111		Not required			
Work / Hy	ygienic prneties				
		Not required			
		rtot roquirou			
	After handling ,wash hand	·			

<sup>&</sup>quot;--" Data