
















Crystal Glass Workstation

NO	PARTS	QTY	NO	PARTS	QTY
A		4	E		2
			F		2
			H		2
			I		2
			J		8
			K		1



NO	PARTS	QTY
B		1
C		1
D		4



Important: Position your desk prior to any equipment being loaded on - do not attempt to move your desk once computer etc are in place.